

October 29, 2019

Department of Environmental Protection  
Division of Air Quality  
601 57<sup>th</sup> Street SE  
Charleston, WV 25304


**RE: Annual NSPS OOOOa Reporting  
August 2, 2018 - August 1, 2019  
Tribune Resources, LLC**

Dear Sir/Madam:

Tribune Resources, LLC (Tribune) owns and operates one (1) Facility in West Virginia that is subject to Title 40 Code of Federal Regulations Part 60 New Source Performance Standards (NSPS) Subpart OOOOa. In compliance with that rule, Altamira-US, LLC (Altamira) is submitting the annual report on behalf of Tribune.

**Statement of Compliance:**

I, Joshua Credeur, certify that I am the Responsible Official, and that, based on information and belief formed after reasonable inquiry, the statements and information contained in this compliance report are true, accurate, and complete.

	<u>10-30-19</u>
Signature	Date
<u>Joshua Credeur / SVP Production - Appalachia</u>	<u>(337) 769-4064</u>
Name/Title	Phone

If you have any questions concerning the report, please contact Shannon Buckley at (405) 541-0545.

Sincerely,  
Altamira-US, LLC

Enclosure

Company Name:	Tribune Resources, LLC
Reporting Period:	August 2, 2018 - August 1, 2019
Reporting:	Site Information

SITE INFORMATION	Facility Record No. *	1
	Company Name * (§60.5420a(b)(1)(i))	Tribune Resources, LLC
	Facility Site Name * (§60.5420a(b)(1)(i))	Mary Miller Wellpad
	US Well ID or US Well ID Associated with the Affected Facility, if applicable. * (§60.5420a(b)(1)(i))	47103030710000 47103030700000 47103030730000 4710303072000
	Address of Affected Facility * (§60.5420a(b)(1)(i))	4435 Hoyt Ridge Road
	Address 2	N/A
	City *	Wileyville
	County *	Wetzel
	State Abbreviation *	WV
	Zip Code *	26581
ALTERNATIVE ADDRESS INFORMATION (IF NO PHYSICAL ADDRESS AVAILABLE FOR SITE *)	Description of Site Location (§60.5420a(b)(1)(i))	N/A
	Latitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (§60.5420a(b)(1)(i))	39.615210
	Longitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (§60.5420a(b)(1)(i))	-80.612490
REPORTING INFORMATION	Beginning Date of Reporting Period.* (§60.5420a(b)(1)(iii))	8/2/2018
	Ending Date of Reporting Period.* (§60.5420a(b)(1)(iii))	8/1/2019
PE CERTIFICATION	Please provide the file name that contains the certification signed by a qualified professional engineer for each closed vent system routing to a control device or process. * (§60.5420a(b)(12)) Please provide only one file per record.	N/A
ADDITIONAL INFORMATION	Please enter any additional information.	N/A
	Enter associated file name reference.	N/A

Company Name: Tribune Resources, LLC  
Reporting Period: August 2, 2018 - August 1, 2019  
Reporting: Well Fracs

	Facility Record No. *	
	United States Well Number* (\$60.5420a(b)(1)(ii))	
All Well Completions	Well Completion ID * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(i))	None to Report

Company Name:

Tribune Resources, LLC

Reporting Period:

August 2, 2018 - August 1, 2019

Reporting:

Fugitives

Identification of Each Affected Facility * (§60.5420a(b)(1))	Mary Miller Wellpad	Mary Miller Wellpad	Mary Miller Wellpad	Mary Miller Wellpad
Date of Survey * (§60.5420a(b)(7)(i))	12/12/2018	12/12/2018	12/12/2018	12/12/2018
Survey Begin Time * (§60.5420a(b)(7)(ii))	9:15	9:15	9:15	9:15
Survey End Time * (§60.5420a(b)(7)(iii))	10:55	10:55	10:55	10:55
Name of Surveyor * (§60.5420a(b)(7)(iii))	Ryan	Ryan	Ryan	Ryan
Ambient Temperature During Survey * (§60.5420a(b)(7)(iv))	27	27	27	27
Sky Conditions During Survey * (§60.5420a(b)(7)(iv))	Overcast	Overcast	Overcast	Overcast
Maximum Wind Speed During Survey * (§60.5420a(b)(7)(iv))	4	4	4	4
Monitoring Instrument Used * (§60.5420a(b)(7)(v))	GF-300 Camera	GF-300 Camera	GF-300 Camera	GF-300 Camera
Deviations From Monitoring Plan (If none, state none.) * (§60.5420a(b)(7)(vi))	Inspections were greater than six months apart.	Inspections were greater than six months apart.	Inspections were greater than six months apart.	Inspections were greater than six months apart.
Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Valve	Thief Hatch	Valve	Valve
Number of Each Component Type for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	1	1	1	1
Type of Component Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	N/A	N/A	N/A	N/A
Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	N/A	N/A	N/A	N/A
Type of Difficult-to-Monitor Components Monitored * (§60.5420a(b)(7)(ix))	N/A	N/A	N/A	N/A
Number of Each Difficult-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	N/A	N/A	N/A	N/A
Type of Unsafe-to-Monitor Component Monitored * (§60.5420a(b)(7)(ix))	N/A	N/A	N/A	N/A
Number of Each Unsafe-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	N/A	N/A	N/A	N/A
Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	12/12/2018	12/12/2018	Heater Taken Out of Service 8/20/2019	Heater Taken Out of Service 8/20/2019
Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	N/A	N/A	Valve	Valve
Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	N/A	N/A	1	1
Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))	N/A	N/A	Requires Shutdown	Requires Shutdown
Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	N/A	N/A	N/A	N/A
Training and Experience of Surveyor * (§60.5420a(b)(7)(iii))	Greater than 1 yr Experience	Greater than 1 yr Experience	Greater than 1 yr Experience	Greater than 1 yr Experience